



## 17041601 NW corner:

CORNER HISTORY: A survey by Wm. B. Laughlin dated 1820 called witness: 10" beech N 62 E 7 links; 7" dogwood 5 57 W 44 links per Marion County Atlas pg. 12. A survey by Paul julian dated 4-5-1894 called stone already set per Washington Township Legal Survey Book pg. 40. Distances were on page 76 same book. Reference dated 1-19-1953 by Monroe called line and distance from stone to the west per Washington Township Legal Survey Book pg. 40. Reference dated 5-11-1987 by Wilcoxen dug for stone at the NW corner of 16-17-4 found a boat spike over  $\frac{3}{4}$ " pipe that was 1.8'W and 1.8'S of stone found 24" down. 1998 a Hamilton County road construction project destroyed the original monumentation for the section corner. The construction contractor was required by the Hamilton County Surveyor's Office to replace the marker with a Harrison Monument. In August 1998 the Marion County Surveyor's Office discovered the Harrison had been set incorrectly. This information was relayed to the Hamilton County Surveyor's Office. With a combined effort by Hamilton and Marion, the original corner location was found using Marion County GPS coordinates established before construction. Hamilton County than reset the Harrison in the original location. July 1998 Marion County again had reason to question the location. Marion County checked the location with GPS coordinates and found the monument was in the correct location. Re-tied by Wilcoxen 7-27-2001.

Re-fled by Wilcoxell 7-27-2001.		-2001.
ŖEF.	DISTANCE	DESCRIPTION
1.	93.19'	Cut 'x' W-bolt of aluminum pole base
2.	114.99'	PK nail w/brass washer NE PwP no# 24"up
3.	90.58'	Cut 'x' N-bolt of aluminum pole base
4.	83.94'	Cut 'x' N-bolt of aluminum pole base
5.	92.60'	Cut 'x' E-bolt of aluminum pole base
6.	147.81	PK nail w/brass washer E PwP#882-1001 24"up